

# Electronic Weight Sensors

OL3000 A, WT1, WT2

## Weight sensors WT1 & WT2

Article number:	WT1 & WT2
Application areas:	Weight sensors for hoisting equipment
Accuracy:	WT1; 10% WT2; 5% Overload use; 1%
Output:	Balanced signal
Power supply:	5V Dc
Size:	WT1; 100 x 65 x 40-50 mm WT2; 15 x 60 x 52-80 mm
Wire size:	WT1; 6-15 mm, 0-3,5T on the unit WT2; 14-28 mm, 0-8,5T on the unit

## Amplifier OL3000A & OL3000C

Article number:	OL3000A, OL3000c
Application:	Amplifier for weight sensors, Din rail mounted
Accuracy:	< 0,1%
Output	4-20 mA
Size:	54 x 90 x 61 mm
Features:	relays (n0) triggers at a user set level



WT1



WT2



OL3000 A